

HAMILTON, NEW YORK

AL-5788 (FAA)

18032

WAAS CH <b>65818</b> <b>W17A</b>	APP CRS <b>170°</b>	Rwy Idg <b>5014</b> TDZE <b>1137</b> Apt Elev <b>1137</b>
--	------------------------	---


# RNAV (GPS) Z RWY 17

HAMILTON MUNI (VGC)

**NA** DME/DME RNP-0.3 NA. Helicopter visibility reduction below 3/4 SM NA. When local altimeter setting not received; use Syracuse altimeter setting and increase LPV DA 167, increase LPV visibility all Cats 1/2 mile.

MISSED APPROACH: Climb to 4000 direct ACAFO and on track 258° to PITCH and on track 343° to GGT VORTAC and hold.



AWOS-3P <b>119.425</b>	SYRACUSE APP CON <b>126.125 269.125</b>	UNICOM <b>123.0</b> (CTAF)	<b>122.7</b> <b>0</b>
---------------------------	--	-------------------------------	-----------------------



NE-2: 16 AUG 2018 to 13 SEP 2018

NE-2: 16 AUG 2018 to 13 SEP 2018

ELEV <b>1137</b>	<b>D</b> TDZE <b>1137</b>
------------------	---------------------------



CATEGORY	A	B	C	D
LPV DA	1464-1¼	327 (400-1¼)		NA

MIRL Rwy 17-35 **0**  
REIL Rws 17 and 35 **0**

HAMILTON, NEW YORK  
Orig-A 30APR15

42°51'N - 75°34'W

# RNAV (GPS) Z RWY 17